Town of Hanover DPW Building Operations Group Closed Work Order Report 07/01/2012 - 05/19/2013

Hanover Police Headquarters

Printed on	Printed on: 05/19/2013		Page: 1		
WO#	Area Description Area Number Description of Problem Action Taken	Priority Status	Requested Date Completed Date	Days Aged	
4389	1st Floor Booking/cells. Prosecutor's office(2nd floor) Two fluorescent light fixtures are in need of new ballast in the booking prosecutor's office.	Medium Complete area. One fluorescent light fixture needs	09/12/2012 09/19/2012 s a ballast in the	7	
4357	Action Taken: replace 1-4 lamp and 2-3 lamp ballasts. 1st Floor communication center Coiling tiles peed replacing. Mold on tiles in communication center. So	Medium Complete	09/10/2012 09/27/2012	17	
	Ceiling tiles need replacing. Mold on tiles in communication center. Some tiles in lower level need replacing as well. Time Available: asap Action Taken: complete done by contractor				
4282	Attic Reinstall loose and fallen insulation under attic roof.	Medium Complete	08/16/2012 09/27/2012	42	
	Action Taken:				
4355	Hallway/Corridor cell and booking areas 4' florescent bulbs need replacing. also a few balusters are not working	Medium Complete g. Time Available: ASAP	09/10/2012 10/10/2012	30	
	Action Taken:				
4649	Gutters need to be cleaned out, heavy vegetation growth in some section not possible to use a latter in this area, will probably need a bucket truc		10/24/2012 10/26/2012 ator and AC compressor it's	2	
	Action Taken: cleaned out on both blds.				
4635	Roof The Cutters on both sides of the building are full and clarged water ru	Medium Complete	10/23/2012 10/26/2012	3	
	The Gutters on both sides of the building are full and clogged, water runs over them. We do not have a ladder to reach so Pete will need an assist with this.				
	Action Taken: done				
i					

Town of Hanover DPW Building Operations Group Closed Work Order Report 07/01/2012 - 05/19/2013

Hanover Police Headquarters

Printed on: (ated on: 05/19/2013		Page: 2			
WO#	Area Description Area Number Description of Problem Action Taken	Priority Status	Requested Date Completed Date	Days Aged		
4648	Grounds The 2 columns outside the front door entrance need to be power washed.We converted to the power washed and the foyer washer columns and the foyer to the foyer washer columns.	Medium Complete do not have a power washer at the station.	10/24/2012 11/13/2012	20		
4752	Medium 11/15/2012 1 sergeant's office Complete 11/16/2012 Key broke off inside office desk lock,it opens but no longer able to lock it.Will need a key extractor tool or should I call a locksmith?(Hanover Lock). Action Taken: Remove broken key.					
4842	Grounds clean leaves	Medium Complete	12/05/2012 12/05/2012	0		
	Action Taken:					
4971	Conference Room training on building automation system.	Medium Complete	12/24/2012 12/24/2012	0		
	Action Taken: Training on police station building automation system.					
5038	drove to police station , library , town hall, senior center with best sprinkler.	Medium Complete	01/04/2013 01/04/2013	0		
	Action Taken:					
5392	Install 2 mounts and flat screens one in Command Center and one in office ren	High Complete move old mounts and monitors.	03/26/2013 03/27/2013	1		
	Action Taken: Remove old TV mounts and install new monitor mounts					

Town of Hanover DPW Building Operations Group Closed Work Order Report 07/01/2012 - 05/19/2013

Hanover Police Headquarters

Requested Date Completed Date	Days Aged			
Grounds Medium Complete 04/02/2013 Metal ground light fixture that lights flag-pole corroded,broke off support stand it will need to be replaced.Bare wires were exposed,I capped them off with wire connectors. Action Taken: Repair connector and re wire light fixture.				
2nd Floor Medium Complete O4/02/2013 O4/11/2013 Comcast recently set up boxes for 2 new tv's chiefs office, and community room. Need to find a way to hide the coaxial cables as they are now just hanging down from the tv ,also need a permanent place for the boxes, they're on tables for now. Action Taken: Install shelves and tie-wrap cables.				
05/09/2013 05/16/2013	7			
	03/04/2013 04/02/2013 e exposed,I 04/02/2013 04/11/2013 cables as they are			

End of report: 3 pages