

**Town of Hanover DPW
Building Operations Group
Open Work Order Report
Cedar School**

Printed on: 05/19/2013

Page: 1

WO #	Area Description Area Number Description of Problem	Priority Status	Requested Date	Days Aged
3385	Classroom 20 Please look at the chalk ledge (in the back by the window). It looks like the wall is crumbling from behind the chalkboard. Can you secure the whiteboard to the wall? Time Available: summer	Medium Work In Progress	06/23/2011	696
4845	Administration Area Main Office Please switch lock handle on the door going from main office into back office/meeting room. Right now there is a key lock going from main office into back office. Handle going from back office into main office has no lock which makes main office always op	Medium Work In Progress	12/05/2012	165
5157	1st Floor kitchen break area the bottom of the door lets water in in a strong west wind. A lot of water! Time Available: any	Medium Work In Progress	01/31/2013	108
5241	Parking Lot back parking lot Some of the lights on poles are on 24/7. I have had complaints that were wasting electricity. Time Available: anytime	Medium Work In Progress	02/27/2013	81
5365	1st Floor rm 15 leak 1 foot from windows in the middle of the room. Time Available: anytime	Medium Work In Progress	03/22/2013	58
5432	Grounds 3rd grade playground There is a manhole cover that sticks up too high on one side. A child tripped and hit his face on the edge of it. A 5 gallon bucket of dirt would make the ground level around it. It is next to the fenced in septic system. Time Available: anytime	Medium Work In Progress	04/04/2013	45
5484	1st Floor boys rm near gym The sensor to turn on the light is not working most of the time. Time Available: anytime	Medium Work In Progress	04/12/2013	37
5546	1st Floor front door front door won't close by itself. It's metal against metal. Time Available: anytime	High Work In Progress Take 1/8 inch off bottom of door (metal door)	05/01/2013	18

**Town of Hanover DPW
Building Operations Group
Open Work Order Report
Cedar School**

Printed on: 05/19/2013

Page: 2

WO #	Area Description Area Number Description of Problem	Priority Status	Requested Date	Days Aged
5578	1st Floor kitchen break room There is a cabinet with a small lock that needs to be cut. They don't know where the key is. Time Available: anytime	Medium Work In Progress	05/09/2013	10

End of report: 2 pages